

# HISTORIC AMERICAN ENGINEERING RECORD

## INDEX TO PHOTOGRAPHS

WICKIUP DAM, OUTLET WORKS

HAER OR-112-A

Deschutes River

La Pine vicinity

Deschutes County

Oregon

Note: original captions for historic photographs and drawings given in uppercase

## INDEX TO BLACK AND WHITE PHOTOGRAPHS

Pamela McKenney, photographer, October 2000

OR-112-A-1	Outlet Works, from foreground: Deschutes River, Stilling Basin, Outlet Opening, Valve House, dam embankment, and Emergency Gates Control Tower, view to southwest
OR-112-A-2	Valve House, Stilling Basin, and Deschutes River with toe drain visible as water fall on left bank, from top of dam embankment, view to north
OR-112-A-3	Toe drain outlet, Deschutes River, view to northwest
OR-112-A-4	Valve House, view to southwest
OR-112-A-5	Valve house, view to south
OR-112-A-6	Valve House, view to east
OR-112-A-7	Valve House, view to north
OR-112-A-8	Valve House interior, tube valves, view to west
OR-112-A-9	WICKIUP DAM OUTLET WORK EXCAVATION BEGINS. Photocopy of historic photograph (original photograph on file at National Archives, Rocky Mountain Region, Denver, CO). Unknown USBR photographer, September 1939

WICKIUP DAM, OUTLET WORKS

HAER OR-112-A

INDEX TO PHOTOGRAPHS

(Page 2)

- OR-112-A-10      CONDUIT EXCAVATION PARTIALLY COMPLETE.  
Photocopy of historic photograph (original photograph on file at National Archives, Rocky Mountain Region, Denver, CO).  
Unknown USBR photographer, October 1939
- OR-112-A-11      DESCHUTES, WICKIUP DAM OUTLET WORKS. STILLING  
BASIN LOOKING UPSTREAM. MONTAG & SONS,  
CONTRACTOR. Photocopy of historic photograph (original  
photograph on file at National Archives, Rocky Mountain Region,  
Denver, CO). Unknown USBR photographer, April 18, 1940
- OR-112-A-12      DESCHUTES. LOOKING UPSTREAM THROUGH OUTLET  
WORKS FROM STATION 12+55 - WICKIUP DAM. Photocopy  
of historic photograph (original photograph on file at National  
Archives, Rocky Mountain Region, Denver, CO). Unknown USBR  
photographer, June 2, 1940
- OR-112-A-13      DESCHUTES. WICKIUP DAM. TWO 96" RING FOLLOWER  
GATE CASTINGS IN PLACE IN GATE CHAMBER. Photocopy  
of historic photograph (original photograph on file at National  
Archives, Rocky Mountain Region, Denver, CO). Unknown USBR  
photographer, June 2, 1940
- OR-112-A-14      DESCHUTES. GENERAL VIEW OF WICKIUP DAM OUTLET  
WORKS CONSTRUCTION LOOKING UPSTREAM FROM  
LEFT BANK. MONTAG & SONS, CONTRACTOR. Photocopy  
of historic photograph (original photograph on file at National  
Archives, Rocky Mountain Region, Denver, CO). Unknown USBR  
photographer, June 2, 1940
- OR-112-A-15      DESCHUTES. WICKIUP DAM OUTLET WORKS, LOOKING  
UPSTREAM. REINFORCING STEEL IN PLACE FOR FLOOR  
OF STILLING BASIN IN FOREGROUND. Photocopy of  
historic photograph (original photograph on file at National  
Archives, Rocky Mountain Region, Denver, CO). Unknown USBR  
photographer, June 17, 1940

WICKIUP DAM, OUTLET WORKS

HAER OR-112-A

INDEX TO PHOTOGRAPHS

(Page 3)

- OR-112-A-16      DESCHUTES. WICKIUP DAM. OPERATING MECHANISM OF 96" RING FOLLOWER GATES IN CONCRETE BLOCK POURED TO ELEV. 4276.25. M.E. WALSH, INSPECTOR. Photocopy of historic photograph (original photograph on file at National Archives, Rocky Mountain Region, Denver, CO). Unknown USBR photographer, June 26, 1940
- OR-112-A-17      DESCHUTES. WICKIUP DAM OUTLET WORKS. RIGHT WALL OF STILLING BASIN PLACING AND REMOVING FORMS. MONTAG & SONS, CONTRACTOR. Photocopy of historic photograph (original photograph on file at National Archives, Rocky Mountain Region, Denver, CO). Unknown USBR photographer, August 5, 1940
- OR-112-A-18      DESCHUTES. WICKIUP DAM OUTLET WORKS. LOOKING DOWNSTREAM THROUGH VALVE HOUSE SUNSTRUCTURE. Photocopy of historic photograph (original photograph on file at National Archives, Rocky Mountain Region, Denver, CO). Unknown USBR photographer, August 5, 1940
- OR-112-A-19      DESCHUTES. WICKIUP DAM OUTLET WORKS. GENERAL VIEW LOOKING UPSTREAM FROM LEFT BANK OF DESCHUTES RIVER. Photocopy of historic photograph (original photograph on file at National Archives, Rocky Mountain Region, Denver, CO). Unknown USBR photographer, August 5, 1940
- OR-112-A-20      DESCHUTES. WICKIUP DAM OUTLET WORKS. LOOKING UPSTREAM, THROUGH STILL BASIN, MONTAG & SONS, CONTRACTOR, POURING CONCRETE IN CENTER WALL. Photocopy of historic photograph (original photograph on file at National Archives, Rocky Mountain Region, Denver, CO). Unknown USBR photographer, August 24, 1940
- OR-112-A-21      DESCHUTES. WICKIUP DAM OUTLET WORKS. PLACING REINFORCING STEEL AND FORMS IN GATE CHAMBER. Photocopy of historic photograph (original photograph on file at National Archives, Rocky Mountain Region, Denver, CO). Unknown USBR photographer, September 26, 1940

WICKIUP DAM, OUTLET WORKS

HAER OR-112-A

INDEX TO PHOTOGRAPHS

(Page 4)

- OR-112-A-22      DESCHUTES. WICKIUP DAM OUTLET WORKS. LOOKING  
UPSTREAM FROM VALVE HOUSE TOWARD GATE  
CHAMBER. Photocopy of historic photograph (original  
photograph on file at National Archives, Rocky Mountain Region,  
Denver, CO). Unknown USBR photographer, October 22, 1940
- OR-112-A-23      DESCHUTES. WICKIUP DAM OUTLET WORKS. GENERAL  
VIEW LOOKING UPSTREAM FROM LEFT BANK OF  
DESCHUTES RIVER. MONTAG & SONS, CONTRACTOR.  
Photocopy of historic photograph (original photograph on file at  
National Archives, Rocky Mountain Region, Denver, CO).  
Unknown USBR photographer, November 24, 1940
- OR-112-A-24      DESCHUTES. WICKIUP DAM OUTLET WORKS. LOOKING  
DOWNSTREAM; AFTER COMPLETION OF MONTAG &  
SONS CONTRACT. Photocopy of historic photograph (original  
photograph on file at National Archives, Rocky Mountain Region,  
Denver, CO). Unknown USBR photographer, November 24, 1940
- OR-112-A-25      DESCHUTES PROJECT - VIEW OF DOWNSTREAM FACE OF  
WICKIUP DAM, VALVE HOUSE AND STILLING BASIN OF  
OUTLET WORKS. Photocopy of historic photograph (original  
photograph on file at National Archives, Rocky Mountain Region,  
Denver, CO). Unknown USBR photographer, August 31, 1943